

# EN6001 – Soft Touch Configuration

## 700244

This application note describes how to configure an EN6001 for operation with a Soft Touch system. For more information on the EN6001 consult 700230E on EntronControls.com.

This document applies to version 7.02 and higher.

#### Sequence of Operation

- 1. The Weld Schedule is initiated in the EN6001 by FS1 or FS2.
- 2. The Valve output SV1 signals the Soft Touch to close the electrodes.
- 3. Once continuity is sensed by the Soft Touch, it outputs a signal to the EN6001 to PI1 or PI3 which must be configured for Second Stage / Before Squeeze.
- 4. PreSqueeze / Squeeze Time begins.
- 5. The Weld 1 segment begins.

### Configuring the EN6001

Use the procedure below to configure the EN6001 to operate with Soft Touch.

1. Become familiar with the membrane button functions used throughout this procedure.





2. Press the **ESC** button until a Status page is displayed. From any Status page press **F** to display the Main Menu.

Main menu
1. Use schedule
2. Edit schedule
<ol> <li>Copy schedule</li> </ol>
4. Reset error
5. Edit counter
L. About

3. **Arrow Down** to highlight **ABOUT**. Hold the **+** button and press **ENTER** to display the Setup menu.

	Main menu
1.	Use schedule
2.	Edit schedule
з.	Copy schedule
4.	Reset error
5.	Edit counter
6.	About

4. Press Arrow Up / Down until CONFIG is highlighted. Press ENTER.



5. **Arrow Down** to highlight **SECOND STAGE.** Press + or – until **BEFORE SQZ** is displayed. Press **ENTER** to save the setting.



- 6. Press **ESC** until the STATUS page is displayed.
- 7. From the Status page press F.

8. Arrow Down to highlight ABOUT

	Main menu
1.	Use schedule
2.	Edit schedule
з.	Copy schedule
4.	Reset error
5.	Edit counter
6.	About

- 9. Hold the + button and press **ENTER** to display the Setup menu.
- 10. Press Arrow Up / Down until I/O MAP is highlighted. Press ENTER.

Setup	
<ol> <li>Config</li> <li>Calibration</li> </ol>	
3. I/O Map	
<ol> <li>Error Map</li> <li>Stepper</li> <li>Utility</li> <li>Ethernet</li> </ol>	

11. Arrow Up / Down to highlight I/O FUNCTION. Press ENTER.



12. Select a Programmable Input 1. (If PI1 us used for another function, select PI3.) Arrow to highlight **PI1.** Press **+** until **2**<sup>nd</sup> **Stage** is displayed. Press **ENTER** to save the change.

I/O Function PI1: 2 <sup>nd</sup> Stage
P12: PS1 P13: Stepper Reset P14: Error Reset P15: Retraction P16: Escape PO1: Retraction PO2: AVC Error

13. Press ESC to display the I/O Map menu. Arrow to PI Source. Press ENTER.



14. **Arrow** to highlight PI1 (or PI3 if it was selected above). Press + until **LOCAL** is displayed. Press **ENTER** to save the change.



- 15. Press **ESC** to display the I/O Map menu.
- 16. Arrow to **SIGNAL SOURCE.** Press ENTER.

1. I/O Function 2. PI Source	
3. Signal Source	

17. Arrow until **2<sup>nd</sup> STAGE** is highlighted. Press **+** until **PI** is displayed. Press **ENTER** to save the change.

Signal Sou	ırce
Error Reset:	PI
TT1:	PI
Interlock:	PI
Edit Lock:	PI
Escape:	PI
Back Step:	PI
2 <sup>nd</sup> Stage:	PI

18. Press **ESC** until the Main Status screen is displayed.

#### Wiring the EN6001 to the Soft Touch

1. For 24Vdc valve outputs connect SV1 (P2-2) and SVC (P2-1) to the Soft Touch Initiation.



2. For 120VAC valves connect the valve to SV1 (PCB2-TS1-SV1) and SV2/SV4/SV6 (PCB2-TS1-SV2SV4SV6)



 The EN6001 can only accept 24Vdc inputs. Connect PI1 (P1-6) and FSC (P1-12) to the Soft Touch Continuity output. If PI3 is used as described above use PI3 (P1-8) and FSC (P1-12)



Terminal	Designation
P1—1	Foot Switch Common
P1—2	Foot Switch #1
P1-3	Foot Switch #2
P1—4	Emergency Stop
P1—5	No Weld Signal
P1—6	Programmable Input #1
P1-7	Programmable Input #2
P1—8	Programmable Input #3
P1—9	Programmable Input #4
P1—10	Programmable Input #5
P1—11	Programmable Input #6
P1—12	Foot Switch Common